### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

### WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-006510 Address: 333 Burma Road **Date Inspected:** 13-Apr-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes Li Zhi jiang/SunWei No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG** Components

### **Summary of Items Observed:**

On this date Caltrans Quality Assurance (QA) Inspector, Lonnie Whitehead, was present during the times noted above for observations relative to the work being performed. BAY#2

This QA Inspector observed the following work in progress:

F.C.A.W. welding for weld joint number 081 on Segment 1AW-Seg003B. Welder is identified as 045260. ZPMC QC is identified as Tian Lei. The welding variables recorded by QC appeared to comply with the applicable WPS.

F.C.A.W. welding for weld joint number 085 on Segment 1AW-Seg003B. Welder is identified as 045240. ZPMC QC is identified as Tian Lei. The welding variables recorded by QC appeared to comply with the applicable WPS.

S.M.A.W. welding for weld joint number 007 on Segment 1AW-Seg003. Welder is identified as 047864. ZPMC QC is identified as Tian Lei. The welding variables recorded by QC appeared to comply with the applicable WPS.

S.M.A.W. welding for weld joint number 008 on Segment 1AW-Seg003. Welder is identified as 047856. ZPMC QC is identified as Tian Lei. The welding variables recorded by QC appeared to comply with the applicable WPS.

## **OUTSIDE AREA**

This QA inspector verified that the following Deck Plates had been completed and the required non destructive

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

testing(NDT) had been performed. Green tags were issued by American Bridge/Flour(ABF).

Component Segment Green Tag# DP277-001 7BW 6409 DP115-002 7BW 6414 DP278-001 7CW 6415

DP116-002 7CW 2777

**BAY#13** 

This QA inspector verified that the following Deck Plates had been completed and the required non destructive testing(NDT) had been performed. Green tags were issued by American Bridge/Flour(ABF).

Component Segment Green Tag# DP334-002 7EE 2778 DP361-001 7EE 2779

**BAY#12** 

This QA inspector verified that the following Deck Plates had been completed and the required non destructive testing(NDT) had been performed. Green tags were issued by American Bridge/Flour(ABF).

Component Segment Green Tag# DP336-001 8BE 2841

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

#### **Summary of Conversations:**

No relevant conversations.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (15000422372), who represents the Office of Structural Materials for your project.

<b>Inspected By:</b>	Whitehead, Lonnie	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer